

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

August 15, 1980

Hazardous Waste Site Inspection - Standard Chlorine Chemical Co., Inc.

Fred N. Rubel, Chief
Emergency Response & Hazardous Materials Inspection Branch

John Frisco, Chief
Uncontrolled Hazardous Waste Site Unit

During the course of our enforcement of the SPCC Plan Program aerial photographic reconnaissance is done in selected areas by the EPA's Advanced Monitoring Systems Division, Environmental Monitoring Systems Laboratory, Las Vegas, Nevada. During one of those missions, a landfill site was identified. See attached copy of photo and photo analysis identified as Site 33.

The site was investigated and the enclosed report on Standard Chlorine Chemical Company describes the results of the site inspection and investigation.

Attachments

CC: Richard Spear

2-SA-ERHMIB:PRElliot:jkw:Bldg.209:X6670

CONCURRENCES						
SYMBOL	SA/ERHMIB	SA/ERHMIB				
SURNAME	ELLIOT	RUBEL				
DATE	8/15/80					

EPA Form 1320-1 (12-70)

332764

OFFICIAL FILE COPY